

Efectis Nederland BV P.O. Box 554 | 2665 ZN Bleiswijk Brandpuntlaan Zuid 16 | 2665 NZ Bleiswijk The Netherlands +31 88 3473 723 nederland@efectis.com

REPORT

Determination of smoke control according to EN 1634-3:2004 + C1:2007 of metal vertical shutter type "B" manufactured by GORTER GROUP BV

Report no. 2023-Efectis-R000940

Sponsor Gorter Group BV

P.O. Box 265

1740 AG SCHAGEN THE NETHERLANDS

Prepared by Efectis Nederland BV

Notified body no. 1234

Author(s) F. Mishahrawi B.Sc.

G.M. Klijn B.Sc.

Project number ENL-23-000364

Date of issue September 2023

Number of pages 25





Efectis Nederland BV 2023-Efectis-R000940 September 2023 Gorter Group BV

REPORT

7.3.1.2

The aspect ratio of the leaf may be changed, subject to the restrictions in 13.2.2.1 and/or 13.2.2.2 and subject to the length of the leakage path not being extended.

7.4 HARDWARE AND FITTINGS

Elements of hardware or ironmongery and/or their fixing technique may not be changed without extended application evaluation.

The positioning of elements of hardware or ironmongery may be modified for ambient temperature (S_a) smoke application but shall not be changed for medium temperature (S_{200}) applications.

7.5 SEALS

As the sealing system is a critical part of the test, no modification may be made to the system tested.

F. Mishahrawi B.Sc. Project Leader Fire Resistance –

and Smoke Control

G.M. Klijn B.Sc. Project Leader Fire Resistance – and Smoke Control